

These tests were conducted in our own laboratory on a range of dimmer models purchased in April 2013. The results are as per the dimmer module specification at the time of testing and any dimmer modifications may affect the dimming performance. In some situations it may be best to trial the dimmer module with our lamps to ensure there are no site issues. The tests were conducted at 230V. If in doubt please contact a member of our sales office on 0845 408 4625.